General Environmental Incident Summary

Incident: 1952 Date/Time Notice: 6/20/2013 1130 DEM Incident No:

Responsible Party: Red Rock Transportation

Date Incident: 6/20/2013 Time Incident: 1030 Duration: 8 hours

Method: Derived from TRS

County: McKenzie Twp: 147 Rng: 98 Sec: 13 Qtr:

Location Description: approx mile post 123 1/2----along Hiway 85---south of Watford City ND----

approx 12 to 13 miles

Submitted By: Robert Pfeifer Affiliation:

Long: -103.11000

Address:

Lat: 47.55241

City: State: Zip:

Received By:

Contact Person: Robert Pfeifer

12590 23rd St NW

Box 646

Watford City, ND 58854

Distance Nearest Occupied Building: 3 Miles

Type of Incident: Vehicle Accident

Description of Released Contaminant: crude oil

Volume Spilled: 3.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

pick up pulled out in front of our truck---driver swirved to miss a collision---dropped wheels off of black top (Hiway 85) causing the trailer to roll over---along with the truck

Risk Evaluation:

High H2S oil

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

soil

Action Taken or Planned:

spill was contained by using booms and absorbant pads until the dirt contractor showed up with an excavavator and side dump trucks to dig out and haul off the contaminated material---excavation is done---approx 3 bbl spill

Wastes Disposal Location: Prarie Disposal---Tioga ND

Agencies Involved: State Highway Patrol, Local Fire Department, Local Law Enforcement

Tuesday, July 29, 2014 Page 1 of 2

Updates

Date: 6/21/2013 Status: Reviewed; Followup Required Staff: Roberts, Kris

Updated Volume:

Notes:

Highway 85 accident. Cleanup reported complete. Please verify no remaining impact.

Date: 6/28/2013 Status: Inspected Staff: Espe, Brady

Updated Volume:

Notes:

Temperature was 75 F°, clear, wind from the southwest 5-10 mph. Pick up pulled out in front of our truck---driver swerved to miss a collision---dropped wheels off of black top (Highway 85) causing the trailer to roll over---along with the truck. Soil was removed and ditch regarded. Did not see any issues with the ditch or road. Looked good. No follow-up required at this time.

Tuesday, July 29, 2014 Page 2 of 2